



2010 PRIUS  
 AUTO NAV LOCKOUT DEFENT  
 18 OCT 2009  
 24





#16

#16 #16

#18 #18

19

DANGER

8 M F 09




BLB

BLB

AR11





135115-2630  
4001273

135115-2630  
4001273

BAT  
BAT



10/17/09 2:00 PM



▼ TEMP ▲  
OFF  
Plasmacluster  
AUTO MODE A/C  
FRONT REAR

10/17/09 2:00 PM





10/17/09 2:00 PM

**TOYOTA**

86120-47390

468100-0582  
**DENSO 12V**

MADE IN JAPAN

SERIAL No. 11401238 0 135000 -5610A101



DENSO CORPORATION  
1-1, Showa-cho, Kariya-shi, Aichi-ken, 448-8661 JAPAN

Manufactured by :  
1, Shinmichi, Takatana-cho, Anjo-shi, Aichi-ken,  
446-8507 JAPAN

This product complies with  
21 CFR Chapter 1. subchapter J.

**TUNING RANGE**

AM 530 to 1710KHZ, FM 87.75 to 107.9MHZ

FCC ID : HYQDNNS025 Type : DNNS025  
IC : 1551A-DNNS025 Canada 310  
This device complies with part 15 of the FCC  
Rules and RSS-210. Operation is subject to  
the following two conditions : (1) This device  
may not cause harmful interference, and (2) this  
device must accept any interference received, includ-  
-ing interference that may cause undesired operation.  
Contains Mercury - Don't Put in trash -  
or Dispose as Hazardous Waste.

E7022

JBL

MAP

MAP



**NOTICE**  
Do not place any objects on the panel.  
Do not leave the panel open when it is not in use.




**CAUTION**  
Do not touch the lens or the disc tray.

**NOTICE** : Insert only one CD into slot at a time. Do not use discs with labels or stickers.

4.1  
28

**TOYOTA**  
86120-47390  
468100-0582  
**DENSO 12V**  
MADE IN JAPAN  
135000  
SERIAL NO. 11401238 0-5810A101  
DENSU CORPORATION  
1-1, Showa-cho, Kariya-shi, Aichi-ken, 488-0261 JAPAN  
Manufactured April 11, 2009



10/17/09 1:27 PM



10/17/09 1:28 PM

